

### Equipment Sent To Supplier

Job Reference :	602245	Date :	10/03/2025
-----------------	--------	--------	------------

#### Equipment Details

Asset Number	: M83593
Serial Number	: 040465
Description	: Viamed - TT480 - RESUSCITATION AID
Department	: BIRTH CENTRE
Fault/Additional Info	: PM

#### Action Required

\* Please select as appropriate.

Please find enclosed the above unit requiring repair/service as previously discussed.

- ☐ These units are covered for repair through a previous agreement.
- ☐ We believe this unit to be under warranty. The unit was purchased on ?? .
- ☐ This has been discussed with your company previously and a fixed price repair of £                      has been agreed. Please use order number                      .

#### Declaration

Is the Item contaminated?	YES Or No	No
---------------------------	-----------	----

Type Of Contamination:

Has the Item been decontaminated?	YES or No	Yes
-----------------------------------	-----------	-----

*This equipment has been decontaminated in accordance with the Trusts Equipment Decontamination Policy.*

Decontamination Method used: Clinell Wipes

Signed : T Holland

Date: 10-3-25

If unit is not covered under contract/warranty, then It would be grateful if a quotation for the repair could be forwarded to enable generation of a Purchase Order.

If you have any queries relating to this matter, please do not hesitate to contact me.

Kind Regards

**Tim Holland**

#### Return Address

EBME

North Manchester General Hospital

Delaunays Road

M8 5RB

\*Please cc EBME.TechnicalNMGH@mft.nhs.uk in any email correspondence  
Telephone : 0161 720 2347