

Service Repair Sheet SRS69057

Contact Name Des Mullan
Company/ Hospital Name Joint Service Sub-Aqua Diving Ce
Department
Position
Direct Phone 0300 1632560
General Phone 0300 163 2560
Opera Account CID32266
Email des.mullan313@mod.gov.uk
Order Number
Date Received 10/Mar/2025
Booked in By Robert Connor
Main Company Vandagraph
Type Return Quote

| | |
|--|--------------------------|
| VIAMEDclean | |
| Goods In Only | |
| Decontamination certificate provided by customer | <input type="checkbox"/> |
| Cleaned by Viamed, if no declaration certificate from customer | <input type="checkbox"/> |
| Signed: _____ | |
| Date: _____ | |
| Goods Out Only | |
| Cleaned by Viamed before returning to customer | |
| Signed: _____ | |
| Date: _____ | |

Notes 05/Mar/2025 Ryan Swaine

05/Mar/2025 Ryan Swaine

TEK-OX has had a battery leak, but still works. To check over and replace any potential problem parts.

10/Mar/2025 Robert Connor

Received 1 x tek-ox s/n TX0032, with yellow case, blue tee, flow diverter, no sensor.

Ready For quote _____

Repair Complete Signed _____

| SRN | Equipment | Stock Ref | Serial Number | Warranty |
|----------|-------------------|-----------|---------------|----------|
| SRN37685 | Vandagraph Tek Ox | | TX0032 | |