

# Service Repair Sheet SRS69033

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Hanson Lijing

Lifemed Medical Supplies

+86 13603093265

852 27108200

00006005

info@lifemed.cn

25/Feb/2025

Robert Connor

Viamed

Warranty

## VIAMEDclean

### Goods In Only

Decontamination  
certificate provided  
by customer ☐

Cleaned by Viamed,  
if no declaration certificate  
from customer ☐

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

### Goods Out Only

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

Notes 13/Feb/2025 Aqib Majeed

13/Feb/2025 Aqib Majeed

customer has 3 faulty UFO 130-2 s stating the Oxygen reading is too low. checked the SN s to see if under warranty, SN891643 warranty has expired, SN155906 expires in May 2025. them both are going to be returned to us, the 3rd sensor was not purchased from Viamed as we have no record of this.

25/Feb/2025 Robert Connor

Received 2 x UFO 130-2 s/n 891643, out of warranty. 155906, still in warranty.

Ready For quote

Careen 4-3-25

Repair Complete Signed

Careen 21-3-25

USD.  
Dist

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37633	Oxygen Sensor	0110081	891643	N
SRN37634	Oxygen Sensor	0110081	155906	Yes

BC. \$30  
Ins.

0140013

@140012 x 1 FOC

S/N, SRS, SRN

~~0110081 x 1~~

~~SRS, SRN.~~

~~0110081 x 1 FOC~~

~~New S/N, SRS, SRN~~

~~0140016 x 1 FOC~~

~~S/N, SRS, SRN~~

Disposed off for customer as requested.

~~BC @ \$30~~

~~Declined.~~

~~Ins @ \$1.65~~

~~UPS x 1 0.20kg 23x15x12cm~~

~~Exp-Saver~~

Ship with Oostand  
\$50.47 order

g 21-3-25