Service Repair Sheet SRS69076

Contact Name

Company/ Hospital Name

Department Position

Direct Phone General Phone Opera Account

Email

Order Number Date Received Booked in By Main Company Type Return Lesley McSporran

Dumfries & Galloway Royal Infirm

Medical Physics Department

Medical Engineering Technician S

01387241816 01387246246

00001480

lesley.mcsporran@nhs.scot

25/Mar/2025 Robert Connor

Viamed Quote

1	VIAMEDclean Goods In Only				
1	Decontamination certificate provided by customer				
	Cleaned by Viamed, if no declaration certificate from customer Signed:				
	Goods Out Only Cleaned by Viamed beforeturning to customer Signed:	ore			

Date:

Notes 21/Mar/2025 Sophie Lines

21/Mar/2025 Sophie Lines

Customer is sending Tom Thumb S/N 440014 for repair - the report the gauge is stuck

25/Mar/2025 Robert Connor

Received 1 x tom thumb s/n 440014, gauge stuck and gauge face chipped. Item was very poorly packaged in an unsealed box and could have been damaged in transit.

Ready For quote

Repair Complete Signed

CGNEEN 26.3.25

Careen 28-3-25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37727	Tom Thumb	0310030	440014	2

0340000 × 1 2 E95 crarged 0.25h1 2 E23.75

5/N, ses, sen

0330203 × 1 2 E128.30

5RS, SEN

0330212 + (2 E3.10

5RS, SEN