North Middlesex University Hospital NHS Trust

North Middlesex University Hospital

Clinical Engineering Main Building Floor Level [-1] Sterling Way, London N18 1QX Email: kamal.pacitti@nhs.net

Tel: 020 88872582

Date of dispatch: 25/03/2025

Our WO#: 123916,123715 and 124785.

io: viame	
5 Station F	
cross Hills,	Keighley
3D20 7DT	
Contact Na	me: Service Dept
E-mail:	steve.hardaker@viamed.co.uk
Tel: +44 (0)1535 634542
Dear Servi	
Please find	enclosed equipment X2 IHC2003 Blenders ref SRS69079
Serial No:	BX1855835,BX1855840 and BX1855831
Please quo	ote us for the cost of the repair by e-mail, so that we can provide you with an
order num	ber.
Fault desc	ription: needs overhauling.
DECONTA	AMINATION (Please tick one)
A)	This equipment is NOT as far as I am aware contaminated by any potentially infected material (eg. Blood/body fluids)
B)	The equipment may be contaminated by potentially infected material
	(eg. Blood/body fluids) and has been decontaminated externally, in accordance with
	the North Middlesex Hospital trust Policy.
-	The equipment may be contaminated with potentially infected material
C)	(eg. Blood/body fluids) but could not be decontaminated.
	(eg. Blood/body fluids) but could flot be decentariant
	inated/potentially hazardous equipment must be despatched in a sealed container/ba
Contam	inated/potentially liazardous equipment mast be despression
	PORT/COLIRIERS NAME: TNT
TRANSP	ORT/COURIERS NAME: TNT

PRINT: SIGN: DATE: