

Service Repair Sheet SRS69075

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Andrew Smith

Golden Jubilee National Hospital

Medical Physics

Clinical Engineer

01419515950

01419515950

00008012

andrew.smith@gjnh.scot.nhs.uk

25/Mar/2025

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer



Cleaned by Viamed,
if no declaration certificate
from customer

Signed: _____

Date: _____



Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 20/Mar/2025 Steve Hardaker

20/Mar/2025 Steve Hardaker

Returning VM-2500-S s/no A1608130010.

Device was dropped, which smashed the screen and it now displays device defective.

25/Mar/2025 Robert Connor

Received 1 x VM 2500-S s/n A1608130010, with silicone cover and 4 x AA battery, screen is cracked.

Ready For quote

CGreen 27-3-25

Repair Complete Signed

CGreen 7-4-25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37728	Capnograph	4410520	A1608130010	N

4440000 x 1 @ £95 per hr = 1/2 hr = £47.50

S/N, SRS, SRN

4430020 x 1 @ £10.15

St. SRS, SRN

UPS x 1 @ £12