

Service Repair Sheet SRS69093

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Sreelakshmy M R Prasad

Whipps Cross University Hospital

Clinical Engineering Department

Clinical Technologist/ Quality Rep

02085356927

02085395522

00003450

s.prasad2@nhs.net

07/Apr/2025

Robert Connor

Viamed

Quote

**VIAMEDclean**

**Goods In Only**

Decontamination  
certificate provided  
by customer ☒

Cleaned by Viamed,  
if no declaration certificate  
from customer ☒

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

**Goods Out Only**

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

Notes 04/Apr/2025 Kate Griffiths

04/Apr/2025 Kate Griffiths

would like to send in 2 x MX300 for calibration. s/n: 331064 and 340499. Will ask for cert of decontamination and batteries removed

07/Apr/2025 Robert Connor

Received 2 x MX300 s/n 331064, 340499, with 6 x AA battery, 2 x coiled cable s/n 0000303, 0010276, 1 x R17V s/n V100943, 1 x R17Vi s/n V100098, with 2 x flow diverter.

Ready For quote

C Green 15.4.25

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37742	Oxygen Monitor	0111235	331064	2
SRN37743	Oxygen Monitor	0111237	340499	2
SRN37744	Oxygen Monitor Cable	0131202	0000303	2
SRN37745	Oxygen Monitor Cable	0131202	0010276	2
SRN37746	Oxygen Sensor	0110018	V100943	Yes
SRN37747	Oxygen Sensor	0110019	V100098	2

0140005 x 0.5hr @ £90 = £47.50

s/n, s/s, s/n

0180029 x 2 @ £45 each

s/s, s/n's

UPS x 1 @ £12.