

**Eric Daniels**CID21216 Opera CID21216 Type: **Vandagraph Retail****Eric Daniels** 6 Moss Carr Grove, Thwaites Brow, Keighley, West Yorkshire, BD21 4SG, United KingdomTel **07915 664907** GBP Retail Price List Vandagraph (0010)[Log Call](#)[Add Issue](#)

Proforma Credit Limit 0.00GBP

[Account Home](#)[Main Details](#)[Account Memos](#)[Sales History](#)[Stock References](#)[Cust./Supp. Returns](#)[Service Visits](#)[Distributor Agreements](#)[Documents Files](#)[Linked Issues](#)[Regulatory Agreements](#)

SRS69106

SRS Created : 15 Apr 2025

Created By Ryan Swaine

[Add Watch](#)[Print Barcodes](#)[Print A4 Sheet](#)[Split Items into Different SRS Numbers](#)[Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description

Choose a file to upload: [Choose file](#) No file chosen[Next](#)

Handle with care

Add Items to Supplier Returns Box

[Add](#)

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

[Add Notes](#)

Service Repair Sheet 69106

Company / Hospital	Eric Daniels
Contact Name	Paul Cook - son in law (local)
Department	
Position	
Company Phone	Paul 07828427632
Direct Phone	Eric 0027836582516
Opera Account	CID21216
Email	suemarydan@gmail.com
Order Number	
Viamed ORD Number	
Date Received Into building	15 Apr 2025
Type	Quote Before Repair Move to Repair
Issues?	

Notes

15/Apr/2025 Ryan Swaine

15/Apr/2025 Ryan Swaine

VN202 mk.1 sn. 0190 & R-17VAN: 109869

Suspected sensor issue, but RS tested sensor in air and is within specification.

Please pass to MG

Items for Repair

... ..

SRN	Equipment	Stock Reference	Barcode	SerialNumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN37760	Oxygen Analyser VN202	7910110 Requires Service Manual Linking in System		0190	VN202	No	No	Unfinished 01 Jan 1970		00:00
SRN37761	Oxygen Sensor Vandagraph	0110217 Requires Service Manual Linking in System	 2372909	109869	Oxygen sensor R-17VAN	Yes	No	Unfinished 01 Jan 1970		00:00

Currently Viewing ITEM SRN37760 Oxygen Sensor Vandagraph 0110217 109869 Oxygen sensor R-17VAN

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	Non added Yet	Non added Yet

▲

ISO REVIEW

Please Select

Instructions