

Service Repair Sheet SRS69100

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Caroline O'Flanagan

The Samson Centre

01483459120

01483459120

00012818

info@samsoncentre.org.uk

14/Apr/2025

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer



Cleaned by Viamed,
if no declaration certificate
from customer

Signed:

RC

Date:

14/4/25



Goods Out Only

Cleaned by Viamed before
returning to customer

Signed:

Date:

Notes 11/Apr/2025 Kate Griffiths

11/Apr/2025 Kate Griffiths

Customer rang. Would like to send in faulty MaxO2 ME Oxygen monitor. S/N given is 8836199009 - unable to find on system. Will ask for nature of fault and ask for cert of decont.

11/Apr/2025 Kate Griffiths

Update: misreading ox levels, they have eliminated batteries/sensor/cable. They have tried monitor on a different ox chamber. Even trying to calib. to air, reading shows either just above zero or very high reading

14/Apr/2025 Robert Connor

Received 1 x MAXO2ME s/n HH36199009.

Ready For quote

Repair Complete Signed

CC, Neen 17.4.25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37757	Oxygen Monitor	0111263	HH36199009	N

0140050 x 1 FOC

S/N, SRS, SRN

No fault found, Returning as requested by customer

UPS x 1 FOC