



Bavaria Blue for Safari

CID**9556** Opera **BAVARIA** Type:**Vandagraph Trade**
Bavaria Blue for Safari 3 Royal Mews, Chilwell, Nottingham, , NG9
 5FZ, UK
 Tel **0115 9431430** GBP Trade Price List Vandagraph (0009)
 Log Call Add Issue
 Proforma Credit Limit 0.00GBP

Proforma Credit Limit 0.00GBP

[Account Home](#)
[Main Details](#)
[Account Memos](#)
[Sales History](#)
[Stock References](#)
[Cust./Supp. Returns](#)
[Service Visits](#)
[Distributor Agreements](#)

SRS69091

SRS Created : 03 Apr 2025
Created By Ryan Swaine
Add Watch

[Print Barcodes](#)
[Print A4 Sheet](#)
[Split Items into Different SRS Numbers](#)
[Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Handle with care
Add Items to Supplier Returns Box

Add

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Linked to Order Reference  **156376**

Service Repair Sheet 69091		Notes
Company / Hospital	Bavaria Blue for Safari	03/Apr/2025 Ryan Swaine
Contact Name	Paul Cooper	03/Apr/2025 Ryan Swaine
Department		TEK-OX - for service and possible needs a new sensor. Please give to MG upon receipt.
Position		07/Apr/2025 Robert Connor
Company Phone	0115 9431430	Received 1 x tek-ox s/n TX0932
Direct Phone	0115 943 1430	
Opera Account	BAVARIA	
Email	pscroyal@outlook.com	
Order Number		
Viamed ORD Number		
Date Received Into building	07 Apr 2025	
Issues?	362256	

Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN37748	Oxygen Analyser TEK-OX	9710203 Requires Service Manual Linking in System	 407674	0932	Oxygen Analyser TEK-OX	No	No	Complete - Repaired 22 Apr 2025 Michael Green	Calibration Problem	01:00

SRN37748 Engineer Notes: **INTERNAL NOTES not for customer discussion**

22/Apr/2025 Michael Green

The Tek-Ox analyser has been repaired. A new case front has been fitted. The R-17VAN Oxygen sensor has been replaced. New batteries have been fitted.

Currently Viewing ITEM SRN37748 Oxygen Analyser TEK-OX 9710203 0932 Oxygen Analyser TEK-OX

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	The Tek-Ox analyser has been repaired. A new case front has been fitted. The R-17VAN Oxygen sensor has been replaced. New batteries have been fitted.	22/Apr/2025 Michael Green The Tek-Ox analyser has been repaired. A new case front has been fitted. The R-17VAN Oxygen sensor has been replaced. New batteries have been fitted.	The Tek-Ox analyser has been repaired. A new case front has been fitted. The R-17VAN Oxygen sensor has been replaced. New batteries have been fitted.

-

ISO REVIEW

Please Select

Instructions