

Service Repair Sheet 69093

Contact Name	Sreelakshmy M R Prasad
Company/ Hospital Name	Whipps Cross University Hospital
Department	Clinical Engineering Department
Position	Clinical Technologist/ Quality Rep.
Direct Phone	02085356927
General Phone	02085395522
Opera Account	00003450
Email	s.prasad2@nhs.net
Order Number	41140098
Date Received	07/Apr/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Calibrated
SRN37742	0111235	331064	Oxygen Monitor	Time :0.5 Hour(s)
Parts Replaced				
	Qty: 1	0180029		
	Qty: 0.5	0140005		

The MX300 Oxygen monitor has been repaired. A calibration check has been performed and a certificate has been produced.

Repair	Ref	S/N	Equipment Type	Calibrated
SRN37743	0111237	340499	Oxygen Monitor	Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0180029		

The MX300 Oxygen monitor has been tested. A calibration check has been performed and a certificate has been produced.

Repair	Ref	S/N	Equipment Type	No Fault Found
SRN37744	0131202	0000303	Oxygen Monitor Cable	Time :0 Hour(s)

The Oxygen sensor cable has been tested. No fault was found.

Repair	Ref	S/N	Equipment Type	No Fault Found
SRN37745	0131202	0010276	Oxygen Monitor Cable	Time :0 Hour(s)

The Oxygen sensor cable has been tested. No fault was found.

Service Repair Sheet 69093

Contact Name	Sreelakshmy M R Prasad
Company/ Hospital Name	Whipps Cross University Hospital
Department	Clinical Engineering Department
Position	Clinical Technologist/ Quality Rep.
Direct Phone	02085356927
General Phone	02085395522
Opera Account	00003450
Email	s.prasad2@nhs.net
Order Number	41140098
Date Received	07/Apr/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37746	0110018	V100943	Oxygen Sensor	No Fault Found Time :0 Hour(s)

The R-17V Oxygen sensor has been tested. The sensor is working within specification.

Repair	Ref	S/N	Equipment Type	
SRN37747	0110019	V100098	Oxygen Sensor	No Fault Found Time :0 Hour(s)

The R-17Vi Oxygen sensor has been tested. The sensor is working within specification.

Repair	Ref	S/N	Equipment Type	
SRN37756	0131202	0000407	Oxygen Monitor Cable	No Fault Found Time :0 Hour(s)

The Oxygen sensor cable has been tested. No fault was found.
