

Service Repair Sheet 69107

Contact Name	Helen Thornton
Company/ Hospital Name	Southern Calibration Laboratories
Position	Office Administrator
Direct Phone	01489790296
General Phone	01489790296
Opera Account	CID22311
Email	support@southcal.co.uk
Order Number	SCL25/0463/5015
Date Received	23/Apr/2025
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	
SRN37780	1410000	PR0490A30	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		

V1000 has had transducer interface cushion replaced and calibration has been checked.

---