

Service Repair Sheet SRS69069
Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Tracy Wang
Justec Shenzhen Co. Ltd

008675526068930
008675526068931
00006027
tracy.wang@justec.cn

31/Mar/2025
Robert Connor
Viamed
Warranty

VIAMEDclean

Goods In Only
Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☐
Signed: _____
Date: _____

Goods Out Only

Cleaned by Viamed before
returning to customer
Signed: _____
Date: _____

Notes 17/Mar/2025 Kate Griffiths

17/Mar/2025 Kate Griffiths

Has a faulty 0110081 - s/n 202153. Under warranty. Email attached has a graph showing the fault.

31/Mar/2025 Robert Connor

Received 1 x UFO 130-2 s/n 202153, with 2 indecipherable images.

Ready For quote

Repair Complete Signed

CCGreen 29.4.25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37736	Oxygen Sensor	0110081	202153	Yes

0140013 x 1 FOC
Old S/N, SRS, SRN

0110081 x 1 FOC
New S/N, SRS, SRN

~~\$166~~ \$166 custom valve.

UPS: Ship with next order.