Service Repair Sheet SRS69085 Contact Name Betti Seredi VIAMEDclean Company/ Hospital Name WQL MED Kft Goods In Only Department Decontamination certificate provided Position Managing Director by customer 0036303395696 **Direct Phone** Cleaned by Viamed, if no declaration certificate 0036303395696 General Phone if no declaration from customer Signed: Opera Account 00006481 Email wql@wql.hu Date: Order Number Goods Out Only
Cleaned by Viamed before returning to customer 24/Apr/2025 Date Received Robert Connor Booked in By Signed: \_\_\_\_ Viamed Main Company Wrong Goods Sent/Ordered Good Type Return Notes 28/Mar/2025 Ryan Swaine 8x R-22MED sensors that have been supplied well over 12 months old and rejected by the end user. Please replace with R-22MEDV sensors upon their return (credit the R-22MED and invoice for the R-22MEDV). Please supply replacements with FOC carriage. I do not believe the R-22MED can go back in to stock, as they are too old, may have to be written off. 24/Apr/2025 Robert Connor 8 x R22MED s/n 956336, 956337, 956338, 956339, 956340, 956343, 956344, 956348

Ready For quote

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37784	Oxygen Sensor	0110022	956336	Yes
SRN37785	Oxygen Sensor	0110022	956337	Yes
SRN37786	Oxygen Sensor	0110022	956338 /	Yes
SRN37787	Oxygen Sensor	0110022	956339	Yes
SRN37788	Oxygen Sensor	0110022	956340	Yes
SRN37789	Oxygen Sensor	0110022	956343 🗸	Yes
SRN37790	Oxygen Sensor	0110022	956344	Yes
SRN37791	Oxygen Sensor	0110022	956348	Yes

Sold Nov 24

Please issue a part Credit on RVM153576-1 for 8x R22 meds refused by end user due to dute of sensor.

Please issue a replacent order for 8x R222medV Pho 0110021 and put carriage as foc as per note from Lyan. cg 6.5.25.

Guro distributer. cost of each sensor £30.20 each.