Service Repair Sheet SRS69103

Contact Name Shelly Dean

Company/ Hospital Name Pullman Instruments (UK) Ltd

Department

Position

 Direct Phone
 01423720360

 General Phone
 01423720360

 Opera Account
 00011971

Email purchasing@pullman.co.uk

Order Number

Date Received 15/Apr/2025 Booked in By Robert Connor

Main Company Viamed Type Return Quote

VIAMEDclean Goods In Only Decontamination certificate provided by customer
Cleaned by Viamed, if no declaration certificate from customer Signed:
Goods Out Only Cleaned by Viamed before returning to customer Signed: Date:

Notes Zero value PO 261562 sent in to ask us to calibrate SPO2 sensor test unit VG900. Last year they sent in one of these with s/n CK62504947 so it may be that. Last time they collected serviced device in person 14/Apr/2025 Kate Griffiths

Zero value PO 261562 sent in to ask us to calibrate SPO2 sensor test unit VG900. Last year they sent in one of these with s/n CK62504947 so it may be that. Last time they collected serviced device in person. Asked for cert of decont 15/Apr/2025 Catherine Spence
With Engineer

Ready For quote <u>CGreen</u> 7.5.25

Repair Complete Signed CGreen 13-5-25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37759	Pulse Oximeter Tester	0013100	CK62504947	7

0083100 × 10 E92.40. 5/10, 5RS, 5RN

EXW. customer to collect G 13.5.25