Service Repair Sheet 69115

Contact Name Oskar Slechta
Company/ Hospital Name Chromservis s.r.o

Position Senior Internal Sales Advisor

 Direct Phone
 420274021221

 General Phone
 420274021221

 Opera Account
 00012607

Email o.slechta@chromservis.eu

Date Received 12/May/2025 Booked in By Robert Connor

Repair Ref S/N Equipment Type Under Warranty

SRN37846 0110122 169712 Oxygen Sensor

Time: 0 Hour(s)

Parts Replaced

Qty: 1 0110122

Replaced under warranty with S/N 239536