

Service Repair Sheet 69077

Contact Name	Mick Smithson
Company/ Hospital Name	Lamboo Medical (UK)
Position	Duty Manager
Direct Phone	0194 2724272
General Phone	01942 724 272
Opera Account	00013111
Email	Mick@lamboo-medical.com
Date Received	02/Apr/2025
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37739	0111276	103625	Oxygen Monitor	Complete - Repaired Time :0 Hour(s)

The MySign O Oxygen monitor has been repaired under warranty. The unit is working as expected.

---

Repair	Ref	S/N	Equipment Type	
SRN37740	0110560	A101442	Oxygen Sensor	No Fault Found Time :0 Hour(s)

The OOM111 Oxygen sensor has been tested.

---