

Service Repair Sheet SRS69077

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Mick Smithson

Lamboo Medical (UK)

Duty Manager

0194 2724272

01942 724 272

00013111

Mick@lamboo-medical.com

02/Apr/2025

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only
Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☒
Signed: RC
Date: 2/4/25

Goods Out Only

Cleaned by Viamed before
returning to customer
Signed: _____
Date: _____

Notes 21/Mar/2025 Steve Hardaker

21/Mar/2025 Steve Hardaker

MySign O s/n 103625 locked up with error code ``Hardware 000 180``.

02/Apr/2025 Robert Connor

Received 1 x MySign O s/n 103625, with sensor cable, CD, battery, t-piece, flow diverter, and OOM111 s/n A101442

Ready For quote

Repair Complete Signed

Cgreen 15.5.25.

| SRN | Equipment | Stock Ref | Serial Number | Warranty |
|----------|----------------|-----------|---------------|----------|
| SRN37739 | Oxygen Monitor | 0111276 | 103625 | Yes |
| SRN37740 | Oxygen Sensor | 0110560 | A101442 | |

*38 Ppt of
GRU*

0140138 x 1 FOC
S/N, SRS, SRN

0140011
~~0140013~~ x 1 FOC
S/N, SRS, SRN

GPS x 1 FOC.