

Service Repair Sheet SRS69135

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Luke Banks

Luke Banks

07770235256

07770235256

CID29122

admin@elroyairmed.com

DVM150164-1

02/Jun/2025

Robert Connor

Viamed

Warranty

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer

Cleaned by Viamed,
if no declaration certificate
from customer

Signed: RC

Date: 2/6/25

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes 27/May/2025 Aqib Majeed

27/May/2025 Aqib Majeed

returning a Max02 Me Monitor SN:JJ60899011 as it has a screen fault, still under warranty

02/Jun/2025 Robert Connor

Received 1 x MAXO2ME s/n JJ60899011, with coiled cable 2375067, MAX550E s/n JJ54299185, flow diverter, 4 x AA battery.

Ready For quote

Repair Complete Signed

CCNOR 5.6.25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37885	Oxygen Monitor	0111263	JJ60899011	Yes
SRN37886	Oxygen Monitor Cable	0131700	Tracking20	
SRN37887	Oxygen Sensor	0110452	JJ54299185	Yes

3

0140000 x 1 FOC

old S/N, SRS, SRN

See below for replacement

0111263 x 1 FOC

New S/N, SRS, SRN

0140011 x 1 FOC

S/N, SRS, SRN

0140025 x 1

S/N, SRS, SRN

UPS x 1 FOC.