

Service Repair Sheet 69144

Contact Name	Paul Weldon
Company/ Hospital Name	Paul Weldon
Direct Phone	07714668104
General Phone	07714668104
Opera Account	CID33271
Email	paul.weldon@panaceatech.co.uk
Date Received	05/Jun/2025
Booked in By	Robert Connor

---

Repair	Ref	S/N	Equipment Type	
SRN37938	7910211	TX1511	Vandagraph Tek Ox	Complete - Repaired Time :0.75 Hour(s)

The battery door battery contact has been replaced. The Tek-Ox is now working as expected.

---