

Service Repair Sheet SRS69142

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Ashley Davies

Thames Medical Ltd

01903522911

01903522911

00011982

ashley@thamesmedical.com

04/Jun/2025

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer



Cleaned by Viamed,
if no declaration certificate
from customer

Signed: _____

Date: _____



Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____

Date: _____

Notes Customer has a VM2500M 80230157 that requires a screen repair due to a crack. Also a damaged power port tho the client does not use the rechargeable battery. They need a quote for the screen repair and a second one for screen repair and power port upgrade

03/Jun/2025 Kate Griffiths

Customer has a VM2500M 80230157 that requires a screen repair due to a crack. Also a damaged power port though the client does not use the rechargeable battery.

They need a quote for the screen repair AND A 2ND ONE for screen repair and power port upgrade. Unable to locate s/n on system

04/Jun/2025 Robert Connor

Received 1 x VM-2500-M-Vet s/n 80230151, with mounting plate and silicone cover, rev 2 power connector, one pin broken off and other 2 bent.

Ready For quote

CGREEN 10-6-25

Repair Complete Signed

CGREEN 17-6-25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37937	Capnograph	4410530	80230151	

Quote 1

4440000 x 0.50hr £47.50
S/N, SRS, SRN

4400080 x 1 @ £42.76
SRS, SRN

4420598 x 1 @ £34.35
SRS, SRN

4430607 x 1 @ £5.10
SRS, SRN

UPS x 1 @ £12.

Quote 2

~~4440000 x 0.25hr £23.75
S/N, SRS, SRN~~

~~4430021 x 1 @ £7.90
SRS, SRN~~

~~UPS x 1 @ £12~~