

Service Repair Sheet 69138

Contact Name	Chris Kavanagh
Company/ Hospital Name	Oxygenixs Limited
Direct Phone	07738 828787
Opera Account	CID14856
Email	chris@thinairsports.com
Date Received	09/Jun/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Replaced
SRN37939	0012749		Misc Bits. See Notes	Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0012749		

The SMARTsat Sensor Connector (6 pin) - Standard Flex Connector Cable (57.9 mm) has been replaced as a good will gesture.
