

North Middlesex University Hospital

NHS Trust

North Middlesex University Hospital
Clinical Engineering
Main Building Floor Level [-1]
Sterling Way, London N18 1QX
Email: kamal.pacitti@nhs.net
Tel: 020 88872582
Date of dispatch: 18/06/2025
Our WO#: 123522,129091 & 131588

To: Viamed Ltd.
15 Station Road
Cross Hills, Keighley
BD20 7DT
Contact Name: Service Dept
E-mail: steve.hardaker@viamed.co.uk
Tel: +44 (0)1535 634542

Dear Service Dept

Please find enclosed equipment X3 IHC2003 Blenders ref SR569158
Serial No: B1307014, BX1854637 and B1305796

Please quote us for the cost of the repair by e-mail, so that we can provide you with an order number.

Fault description: needs overhauling.

DECONTAMINATION (Please tick one)

- A) This equipment is NOT as far as I am aware contaminated by any potentially infected material (eg. Blood/body fluids)
- B) The equipment may be contaminated by potentially infected material (eg. Blood/body fluids) and has been decontaminated externally, in accordance with the North Middlesex Hospital trust Policy.
- C) The equipment may be contaminated with potentially infected material (eg. Blood/body fluids) but could not be decontaminated.

Contaminated/potentially hazardous equipment must be despatched in a sealed container/bag

TRANSPORT/COURIERS NAME: TNT

PRINT: _____

SIGN: _____

DATE: _____