

Service Repair Sheet 69137
Contact Name Sudath Weeraman
Company/ Hospital Name Prime Lanka Associate
Direct Phone 9410718732285
Opera Account 00006714
Email sudathweeraman17@gmail.com
Date Received 16/Jun/2025
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37952	0110049	V104860	Oxygen Sensor	

Parts Replaced

Qty: 1 0110049

Time :0 Hour(s)

Replaced under warranty with S/N V105351
