

Service Repair Sheet 69177

Contact Name	Stephen Machin
Company/ Hospital Name	Prosol UK Sales & Distribution Ltd
Department	Purchasing/Sales
Position	Operations Manager
Direct Phone	01142557700
General Phone	01142557700
Opera Account	00020046
Email	stephen@prosol.co.uk
Date Received	07/Jul/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37982	0110365	P106590	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN37983	0110122	218618	Oxygen Sensor	No Fault Found Time :0 Hour(s)

No fault found.

Repair	Ref	S/N	Equipment Type	End Of Life
SRN37984	0110122	793096	Oxygen Sensor	Time :0 Hour(s)

End of life. Disposed of.