

Service Repair Sheet 69191
Contact Name Martin Scott
Company/ Hospital Name Hull Royal Infirmary
Department Clinical Engineering Department
General Phone 01482608783
Opera Account 00002265
Email martin.scott7@nhs.net
Date Received 21/Jul/2025
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38010	0110040	V108401	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108513.

This a different batch.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38011	0110040	V108402	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108514.

This has been confirmed as a different batch.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38012	0110040	V108403	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108515.

This has been confirmed as a different batch.
