

Service Repair Sheet SRS69120

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Mr Mahesha

BDI India Private Limited

Customer Support

Customer Support

918022560418

918022560418

00006454

mahesha@bdi-india.com

12/May/2025

Robert Connor

Viamed

Quote

VIAMEDclean

Goods In Only

Decontamination
certificate provided
by customer ☒

Cleaned by Viamed,
if no declaration certificate
from customer ☒

Signed: RC
Date: 12/5/25

Goods Out Only

Cleaned by Viamed before
returning to customer

Signed: _____
Date: _____

Notes 06/May/2025 Kate Griffiths

06/May/2025 Kate Griffiths

5 V1000s to be sent in for calibration. Have asked for them to be cleaned before sending and asked for cert of decontamination/batteries removed. S/N: PR02529A24, PR02529A12, PR02529A10, PR02380A12 and PR02380A14

08/May/2025 Kate Griffiths

Update, they say it will be shipped 9.5.25 by DHL

12/May/2025 Robert Connor

5 x V1000 s/n PR02529A10, with battery door and grey silicone cover, PR02529A12, with battery door from PR03142A12, PR02529A24, missing battery door, PR02380A14, with battery door, and PR02540A12, with battery door from PR02380A12. Units need thorough cleaning.

Ready For quote

CGreen 14.5.25

Repair Complete Signed

CGreen 28.7.25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37848	Foetal Simulator	1410000	PR02529A10	22
SRN37849	Foetal Simulator	1410000	PR02529A12	22
SRN37850	Foetal Simulator	1410000	PR02380A14	22
SRN37851	Foetal Simulator	1410000	PR02529A24	22
SRN37852	Foetal Simulator	1410000	PR02540A12	22

1480000 x 5 @ £63.40
S/N's, SRS, SRN

1430309 x 5 @ FOC
SRS, SRN

1440001
~~1430288~~ x 1 @ \$66.00
BC. \$35.00

Exw. 32x24x24cm 3kg