Service Repair Sheet SRS69151

Contact Name

B₂B

Company/ Hospital Name

Pinderfields General Hospital

Department

Position Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received Booked in By

Main Company Type Return

01924 201688

00005190

midyorks.accountspayable@nhs

10/Jun/2025

Robert Connor

Viamed Quote

	VIHMEDCIEAN					
	Goods In Only Decontamination certificate provided by customer					
s.r	Cleaned by Viamed, if no declaration certificate from customer Signed:					
	Goods Out Only Cleaned by Viamed before returning to customer					

Date:

Notes 10/Jun/2025 Robert Connor 10/Jun/2025 Robert Connor

Returned 1 x TOF3D s/n T3D202101016, with patient lead and transducer clips, battery compartment unchecked, accelerometer lead missing. Transducer lead was tightly wrapped and tied around patient lead on receipt. Customer reports fault as damaged screen and missing accessories.

Ready For quote

CGNean 30.7.25

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37947	Microstim	2510091	T3D202101016	7

2540100 × 0.75 @ E95per hr SIN, SES, SEN

2530140 ×1 E209.60 SRS, SRN

OPSXI DE12.