

Service Repair Sheet 69015

Contact Name	Diana Rrushi
Company/ Hospital Name	Omniacell Tertia S.R.L
Direct Phone	390558068060
General Phone	00390558068060
Opera Account	CID12447
Email	diana@omniacelltertia.it
Date Received	28/Jul/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38079	1410000	PR03372A15	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38080	1410000	PR03488A13	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38081	1410000	PR03488A14	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38082	1410000	PR03507A10	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.
