

# Service Repair Sheet SRS69203

Contact Name Ian Stanley  
 Company/ Hospital Name Basildon Hospital  
 Department MEMS  
 Position Medical Technician  
 Direct Phone 03004438131  
 General Phone 01268524900  
 Opera Account 00001965  
 Email ian.stanley@nhs.net  
 Order Number  
 Date Received 05/Aug/2025  
 Booked in By Robert Connor  
 Main Company Viamed  
 Type Return Warranty

**VIAMEDclean**  
**Goods In Only**  
 Decontamination certificate provided by customer ☒  
 Cleaned by Viamed, if no declaration certificate from customer ☐  
 Signed: \_\_\_\_\_  
 Date: \_\_\_\_\_

**Goods Out Only**  
 Cleaned by Viamed before returning to customer  
 Signed: \_\_\_\_\_  
 Date: \_\_\_\_\_

Notes 04/Aug/2025 Kate Griffiths  
 04/Aug/2025 Kate Griffiths  
 has 2 x 0110043, s/n: V111150 and V111128. In the incubator, they could not get the correct O2 levels. Other sensors passed first time. Under warranty  
 05/Aug/2025 Robert Connor  
 Received 2 x R43V s/n V111150, V111128.

Ready For quote

Repair Complete Signed

CGreen 6.8.25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38097	Oxygen Sensor	0110043T	V111128	Yes
SRN38098	Oxygen Sensor	0110043T	V111150	Yes

3 matched pair

0140013 x 1 FOC  
 Old S/N, SRS, SRN

0110043 x 2 FOC  
 New S/N, SRS, SRN

UPS x 1 FOC.