

Service Repair Sheet SRS69203

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Ian Stanley

Basildon Hospital

MEMS

Medical Technician

03004438131

01268524900

00001965

ian.stanley@nhs.net

**VIAMEDclean**

**Goods In Only**

Decontamination  
certificate provided  
by customer ☒

Cleaned by Viamed,  
if no declaration certificate  
from customer ☐

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

**Goods Out Only**

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

Notes 04/Aug/2025 Kate Griffiths

04/Aug/2025 Kate Griffiths

has 2 x 0110043, s/n: V111150 and V111128. In the incubator, they could not get the correct O2 levels. Other sensors passed first time. Under warranty

05/Aug/2025 Robert Connor

Received 2 x R43V s/n V111150, V111128.

Ready For quote

Repair Complete Signed

CGreen 6.8.25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38097	Oxygen Sensor	0110043T	V111128	Yes
SRN38098	Oxygen Sensor	0110043T	V111150	Yes

3 matched pair

0140013 x 1 FOC  
old S/N, SRS, SRN

0110043 x 3 FOC  
New S/N, SRS, SRN

UPS x 1 FOC.