

# Service Repair Sheet SRS69200

Contact Name  
Company/ Hospital Name  
Department  
Position  
Direct Phone  
General Phone  
Opera Account  
Email  
Order Number  
Date Received  
Booked in By  
Main Company  
Type Return

Ross Bowden  
Cardiff and Vale UHB  
Clinical Engineering  
  
02921845678  
029 2090 3794  
00000092  
Ross.Bowden@wales.nhs.uk

05/Aug/2025  
Robert Connor  
Viamed  
Quote

## VIAMEDclean

**Goods In Only**  
Decontamination  
certificate provided  
by customer ☒

Cleaned by Viamed,  
if no declaration certificate  
from customer ☒  
Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

## Goods Out Only

Cleaned by Viamed before  
returning to customer  
Signed: \_\_\_\_\_  
Date: \_\_\_\_\_

Notes 29/Jul/2025 Kate Griffiths

29/Jul/2025 Kate Griffiths

customer has 2 x AX-300i that no longer give readings. S/n: 291148 and 322566. They have tried replacing the cells/cables. Will ask for cert of decont. and no batteries

31/Jul/2025 Kate Griffiths

1Z43E45E6896981680 tracking number 31.7.25

05/Aug/2025 Robert Connor

Received 2 x AX300i s/n 291148, 322566, with 2 x base stand, 2 x coiled cable, 2 x flow diverter, 2 x R17MED s/n 953550, 571959, with 1 x blue tee.

Ready For quote

Repair Complete Signed

CGNEON 11-8-25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38087	Oxygen Analyser	0111230	291148	2
SRN38088	Oxygen Analyser	0111230	322566	2
SRN38089	Oxygen Sensor	0110017	571959	2
SRN38090	Oxygen Sensor	0110017	953550	2
SRN38091	Misc. Cable	0131202	0014516	2
SRN38092	Misc. Cable	0131202	0012289	2

01400004 x 0.5 @ £90 = £47.50

S/N, SRS, SRN

0121216 x 1 @ £46.20

SRS, SRN

01800001 x 1 @ £50

S/N, SRS, SRN

01400012 x 2 FOC

S/N's, SRS, SRN's

0110017 x 2 @  
SRS, SRN's £54.40  
each

UPS x 1 @ £12.