

★ Ryan Swaine 20 Issues 11 Unread 10 ISO Tasks | [My Requests 25.40 °C](#) Contacts »

         

 



**G GEORGANTAS KAI
SIA EE**

CID33883 Opera CID33883 Type:Vandagraph Trade

[G GEORGANTAS KAI SIA EE](#) SCUBAKRETA, Inside Nana Golden Beach, Hersonissos, Crete, , 70014, Greece

Tel **00306936893032** GBP Trade Price List Vandagraph (0009)

[Log Call](#) [Add Issue](#)

Proforma Credit Limit 0.00GBP

VAT EL997109121

[Account Home](#) [Main Details](#) [Account Memos](#) [Sales History](#) [Stock References](#) [Cust./Supp. Returns](#) [Service Visits](#) [Distributor Agreements](#)

[Documents Files](#) [Linked Issues](#) [Regulatory Agreements](#)

SRS69192

SRS Created : 17 Jul 2025

Created By Ryan Swaine

[Add Watch](#)

[Print Barcodes](#)

[Print A4 Sheet](#)

[Split Items into Different SRS Numbers](#)

[Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Handle with care

Add Items to Supplier Returns Box

[Add](#)

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System. -
will apply to all items on srs

Add notes to SRS

[Add Notes](#)

Service Repair Sheet 69192		Notes
Company / Hospital	G GEORGANTAS KAI SIA EE	17/Jul/2025 Ryan Swaine
Contact Name	Katerina Georganta	17/Jul/2025 Ryan Swaine
Department		TEK-OX sn. TX2146, suffered battery or sensor leak. Blue liquid found in battery/sensor compartment. Quote for repair and new sensor.
Position		05/Aug/2025 Robert Connor
Company Phone	00306936893032	Received 1 x Tek-ox s/n TX2146, with blue tee and yellow case.
Direct Phone	00306936893032	
Opera Account	CID33883	
Email	kati.geo@hotmail.com	
Order Number		
Viamed ORD Number		
Date Received Into building	05 Aug 2025	
Type	Quote Before Repair Move to Repair	

Issues?

Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN38095	Vandagraph Tek Ox	7910211 Requires Service Manual Linking in System	 818806	TX2146	Oxygen Analyser Tek-Ox	No	No	Unfinished		00:00

SRN38095 Engineer Notes: **INTERNAL NOTES not for customer discussion**
11/Aug/2025 Michael Green
The Tek-Ox analyser has been tested. The unit has suffered a battery leak. The battery contacts seem to be in good condition. The wiring loom is showing signs of galvanic corrosion and should be replaced.

Currently Viewing ITEM SRN38095 Vandagraph Tek Ox 7910211 TX2146 Oxygen Analyser Tek-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	11/Aug/2025 Michael Green The Tek-Ox analyser has been tested. The unit has suffered a battery leak. The battery contacts seem to be in good condition. The wiring loom is showing signs of galvanic corrosion and should be replaced.	Non added Yet

ISO REVIEW

Please Select

Instructions