



NHS
WALES
GIG
CYMRU

No: 75747

INSPECTION, SERVICE, REPAIR OR TRANSPORT
OF MEDICAL AND LABORATORY ITEMS/EQUIPMENT

CLEARANCE CERTIFICATE HS/CC/95

This item/equipment will NOT be accepted unless the following information is completed in full

1 TO VIAMED LTD. FROM CLINICAL ENGINEERING
15, STATION ROAD CARDIFF AND VALE ULHB
CROSS HILLS 20, FIELD WAY, HEATH, CARDIFF
KEIGHLEY, BD20 7DT CF14 4HY TEL 02921845678

2 Description of item/equipment OXYGEN ANALYSER, AX300-I
Bar code/serial no. 291148+322566 Order/Requisition No: SRS69200

Please answer all questions by circling YES or NO and give further details in the space provided.

3. Has this item/equipment been exposed internally or externally to hazardous materials as indicated below?

Provide further details here

YES <input checked="" type="radio"/> NO	Blood, tissue, body fluids, respired gases, pathological samples, etc.	
YES <input checked="" type="radio"/> NO	Chemicals or substances hazardous to health.	
YES <input checked="" type="radio"/> NO	Other hazards/biohazards.	

4. Has the item/equipment been suitably decontaminated? *If YES, indicate method and materials*

YES <input checked="" type="radio"/> NO	External	
YES <input checked="" type="radio"/> NO	Internal	<u>CLINELL WIPES</u>

5. Has the item/equipment been suitably prepared to ensure safe handling/transportation?

YES <input checked="" type="radio"/> NO	<u>SECURELY PACKAGED</u>
---	--------------------------

6. Has the item/equipment been involved in a reportable incident or occurrence (see notes)?

YES <input checked="" type="radio"/> NO	
---	--

7. Authorised signature RQL Name (print) ROSS BOWDEN

Designation MEDICAL DEVICES IT LEAD Date 30/07/2025 Tel. No: 02921845678

ADDITIONAL INFORMATION OR FAULT REPORT

8. Please give as much detail as possible 2 x AX300-I OXYGEN ANALYSERS
NO LONGER GIVING READINGS. NEW SENSOR CABLES AND
CELLS FITTED WITHOUT SUCCESS.