

Service Repair Sheet 69190

Contact Name	Morne Leukes
Company/ Hospital Name	SSEM Mthembu Medical (Pty) Ltd
Position	National Technical Manager
Direct Phone	0027114307000
General Phone	000114307000
Opera Account	CID11237
Email	mornel@ssemthembu.co.za
Order Number	SRS69190
Date Received	28/Jul/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38083	1410000	PR02810A10	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38084	1410000	PR02810A11	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38085	1410000	PR02810A14	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.

Repair	Ref	S/N	Equipment Type	
SRN38086	1410000	PR02810A15	Foetal Simulator	Complete - Repaired Time :0 Hour(s)

Parts Replaced

Qty: 1	1480000
Qty: 1	1430309

V1000 has had transducer interface cushion replaced and calibration has been checked.
