Service Repair Sheet SRS69158

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Kamal Pacitti

North Middlesex University Hospit

Clinical Engineering Department

Specialist Clinical Engineer

02088873790

02088872000

00003070

kamal.pacitti@nhs.net

18/Jun/2025

Robert Connor

Viamed

Quote

VIAMEDclean Goods In Only Decontamination Z certificate provided by customer Cleaned by Viamed, if no declaration certificate from customer Signed: Date:

Goods Out Only

Cleaned by Viamed before returning to customer

Signed:

Date:

Notes 3 x Blenders for overhaul service, serial numbers to be advised 17/Jun/2025 Catherine Spence Updated Serial Numbers. B1307014,BX1854637 and B1305796

18/Jun/2025 Robert Connor

Received 3 x blender s/n BX1854637, B1307014, B1305796.

Ready For quote

CGREEN 10.6.25 CGREEN 14-8-25

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN37955	Blender	0310200	B1305796	2
SRN37956	Blender	0310200	B1307014	2
SRN37957	Blender	0310200	BX1854637	2

0380019 x 3 2 E390 each SIN'S SES, SEN'S

0332001 x 3 FOC 5RS, SRN'S UPS x 1 2 E12.