

Service Repair Sheet SRS69207

Contact Name Jorge Santana
 Company/ Hospital Name East Surrey Hospital
 Department
 Position
 Direct Phone 01737768511 x6044
 General Phone 01737768511
 Opera Account 00004300
 Email Jorge.Santana@nhs.net
 Order Number
 Date Received 15/Aug/2025
 Booked in By Robert Connor
 Main Company Viamed
 Type Return Warranty

VIAMEDclean

Goods In Only

Decontamination
 certificate provided
 by customer ☒

Cleaned by Viamed,
 if no declaration certificate
 from customer ☒

Signed: _____

Date: _____

Goods Out Only

Cleaned by Viamed before
 returning to customer

Signed: _____

Date: _____

Notes 4x R-30V, leaking gas through connector. This fault is known to Honeywell (SRS69175). Please replace the sensors free of charge. sn. V108446, V108258, V108449, V108447

15/Aug/2025 Robert Connor

Received 4 x R-30V s/n V108258, V108446, V108447, V108449.

Ready For quote

Repair Complete Signed

C Green 20.8.25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38109	Oxygen Sensor	0110040	V108258	Yes
SRN38110	Oxygen Sensor	0110040	V108446	Yes
SRN38111	Oxygen Sensor	0110040	V108447	Yes
SRN38112	Oxygen Sensor	0110040	V108449	Yes

0140013 x 4 FOC
 old S/N's, SRS, SRN

0110040 x 4 FOC
 new S/N, SRS, SRN

UPS x 1 FOC.