

Service Repair Sheet 69207

Contact Name	Jorge Santana
Company/ Hospital Name	East Surrey Hospital
Direct Phone	01737768511 x6044
General Phone	01737768511
Opera Account	00004300
Email	Jorge.Santana@nhs.net
Date Received	15/Aug/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38109	0110040	V108258	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108550.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38110	0110040	V108446	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108551.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38111	0110040	V108447	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108552.

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38112	0110040	V108449	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108553.