Service Repair Sheet SRS69213

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Tracy Tidbury

Coventry University Hospital

MEBS

MEBS Materials Management Spe

02476968378

02476964000

00001288

tracy.tidbury@uhcw.nhs.uk

18/Aug/2025

Robert Connor

Viamed

Warranty



Notes 14/Aug/2025 Sophie Lines

14/Aug/2025 Sophie Lines

Customer received 15x 0110040 in June on PO 999007898 - they say they are faulty as they do not seal proprerly when fitted to a machine and are causing leaks. They currently have 13 units quarantined in a box. Advised they return for investigation and if found to be faulty we will provide warranty replacements.

14/Aug/2025 Sophie Lines

Ryan advised Please make a note on the SRS to send them back to Envitec, as they have a gas leak problem, and we should replace them to the end user

14/Aug/2025 Sophie Lines

As per Steve - please replace as soon as received.

18/Aug/2025 Robert Connor

Received 13 x R30V s/n V108469, V108470, V108472, V108473, V108474, V108475, V108476, V108478, V108479, V108480, V108481, V108482, V108483.

Ready For quote

Repair Complete Signed

CGNEON 20-8.25

	SRN	Equipment	Stock Ref	Serial Number	Warranty
	SRN38117	Oxygen Sensor	0110040	V108469	Yes
ı	SRN38118	Oxygen Sensor	0110040	V108470	Yes
	SRN38119	Oxygen Sensor	0110040	V108472	Yes
	SRN38120	Oxygen Sensor	0110040	V108473	Yes
	SRN38121	Oxygen Sensor	0110040	V108474	Yes
	SRN38122	Oxygen Sensor	0110040	V108475	Yes
	SRN38123	Oxygen Sensor	0110040	V108476	Yes
	SRN38124	Oxygen Sensor	0110040	V108478	Yes
	SRN38125	Oxygen Sensor	0110040	V108479	Yes
	SRN38126	Oxygen Sensor	0110040	V108480	Yes
	SRN38127	Oxygen Sensor	0110040	V108481	Yes
	SRN38128	Oxygen Sensor	0110040	V108482	Yes
	SRN38129	Oxygen Sensor	0110040	V108483	Yes

0140013 x 13 FOC

0110040 x 13 FOC New S/N, Ses, SEN

UPS x 1 FOC.