

Service Repair Sheet 69213

Contact Name	Tracy Tidbury
Company/ Hospital Name	Coventry University Hospital
Department	MEBS
Position	MEBS Materials Management Specialist
Direct Phone	02476968378
General Phone	02476964000
Opera Account	00001288
Email	tracy.tidbury@uhcw.nhs.uk
Date Received	18/Aug/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38117	0110040	V108469	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108650

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38118	0110040	V108470	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108651

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38119	0110040	V108472	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108652

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38120	0110040	V108473	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108653

Service Repair Sheet 69213

Contact Name	Tracy Tidbury
Company/ Hospital Name	Coventry University Hospital
Department	MEBS
Position	MEBS Materials Management Specialist
Direct Phone	02476968378
General Phone	02476964000
Opera Account	00001288
Email	tracy.tidbury@uhcw.nhs.uk
Date Received	18/Aug/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38121	0110040	V108474	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108654

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38122	0110040	V108475	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108655

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38123	0110040	V108476	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108656

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38124	0110040	V108478	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108657

Service Repair Sheet 69213

Contact Name	Tracy Tidbury
Company/ Hospital Name	Coventry University Hospital
Department	MEBS
Position	MEBS Materials Management Specialist
Direct Phone	02476968378
General Phone	02476964000
Opera Account	00001288
Email	tracy.tidbury@uhcw.nhs.uk
Date Received	18/Aug/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38125	0110040	V108479	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108658

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38126	0110040	V108480	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108659

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38127	0110040	V108481	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108660

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38128	0110040	V108482	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108661

Service Repair Sheet 69213

Contact Name	Tracy Tidbury
Company/ Hospital Name	Coventry University Hospital
Department	MEBS
Position	MEBS Materials Management Specialist
Direct Phone	02476968378
General Phone	02476964000
Opera Account	00001288
Email	tracy.tidbury@uhcw.nhs.uk
Date Received	18/Aug/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Under Warranty
SRN38129	0110040	V108483	Oxygen Sensor	

Time :0 Hour(s)

Parts Replaced

Qty: 1 0110040

Replaced under warranty with S/N V108662
