

# Service Repair Sheet SRS69201

Contact Name

Company/ Hospital Name

Department

Position

Direct Phone

General Phone

Opera Account

Email

Order Number

Date Received

Booked in By

Main Company

Type Return

Jim S

Benson Medical Industries Inc

0019054750401

0019054750401

00006089

service@bensonmedical.ca

05/Aug/2025

Robert Connor

Viamed

Quote

## VIAMEDclean

### Goods In Only

Decontamination  
certificate provided  
by customer



Cleaned by Viamed,  
if no declaration certificate  
from customer

Signed: \_\_\_\_\_

Date: \_\_\_\_\_



### Goods Out Only

Cleaned by Viamed before  
returning to customer

Signed: \_\_\_\_\_

Date: \_\_\_\_\_

Notes 31/Jul/2025 Kate Griffiths

31/Jul/2025 Kate Griffiths

Benson have a client with VM2500-S issues. S/N: A1906160003. Not reading CO2 correctly. Reads flat or low does not correspond to breathing pattern. Then stops and begins to flash red around connection point. MORE INFO in email attached

05/Aug/2025 Robert Connor

Received 1 x VM-2500-S-Vet s/n A190610003, with li-poly battery.

Ready For quote

CCGreen 29.8.25

GBP Dist

Repair Complete Signed

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38094	Capnograph	4410540	A1906160003	N

4440000 x 4 @ £95 per hr = £71.25  
S/N, SRS, SRN

4480520 x 1 @ £105  
SRS, SRN.

4420504 x 1 @ £807.50  
SRS, SRN

4430201 x 1 @ £154.60  
SRS, SRN

4430200 x 1 @ £10.40  
SRS, SRN

4430120 x 1 @ £125.60  
SRS, SRN

4430115 x 1 @ £10.30  
SRS, SRN

UPS x 1 Exp-Sav-  
32x24x14cm