

Service Repair Sheet 69205
Contact Name Katy Romanowski
Company/ Hospital Name Tenacore LLC
Direct Phone 008002972241
General Phone 008002972241
Opera Account 00007996
Email Katy.Romanowski@tenacore.com
Date Received 15/Aug/2025
Booked in By Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38113	1410000	PR02976A11	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		

V1000 has had transducer interface cushion replaced and calibration has been checked.
