

Service Repair Sheet SRS69200

Contact Name Ross Bowden
 Company/ Hospital Name Cardiff and Vale UHB
 Department Clinical Engineering
 Position
 Direct Phone 02921845678
 General Phone 029 2090 3794
 Opera Account 00000092
 Email Ross.Bowden@wales.nhs.uk
 Order Number
 Date Received 05/Aug/2025
 Booked in By Robert Connor
 Main Company Viamed
 Type Return Quote

VIAMEDclean

Goods In Only

Decontamination
 certificate provided
 by customer ☒

Cleaned by Viamed,
 if no declaration certificate
 from customer

Signed: _____
 Date: _____

Goods Out Only

Cleaned by Viamed before
 returning to customer

Signed: _____
 Date: _____

Notes 29/Jul/2025 Kate Griffiths

29/Jul/2025 Kate Griffiths

customer has 2 x AX-300i that no longer give readings. S/n: 291148 and 322566. They have tried replacing the cells/cables. Will ask for cert of decont. and no batteries

31/Jul/2025 Kate Griffiths

1Z43E45E6896981680 tracking number 31.7.25

05/Aug/2025 Robert Connor

Received 2 x AX300i s/n 291148, 322566, with 2 x base stand, 2 x coiled cable, 2 x flow diverter, 2 x R17MED s/n 953550, 571959, with 1 x blue tee.

Ready For quote

Repair Complete Signed

CCNEEN 18-11-8-25

CCNEEN 3-9-25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38087	Oxygen Analyser	0111230	291148	2
SRN38088	Oxygen Analyser	0111230	322566	2
SRN38089	Oxygen Sensor	0110017	571959	2
SRN38090	Oxygen Sensor	0110017	953550	2
SRN38091	Misc. Cable	0131202	0014516	2
SRN38092	Misc. Cable	0131202	0012289	2

01400004 x 0.5 @ £90 = £47.50

S/N, SRS, SRN

0121216 x 1 @ £46.20

SRS, SRN.

01800001 x 1 @ £50

S/N, SRS, SRN

0140012 x 2 FOC

S/N's, SRS, SRN's

0110017 x 2 @
 SRS, SRN's £54.40
 each

* 0140025 x 2
 S/N's, SRS, SRN's
 UPS x 1 @ £12.