

Service Repair Sheet 69200

Contact Name	Ross Bowden
Company/ Hospital Name	Cardiff and Vale UHB
Department	Clinical Engineering
Direct Phone	02921845678
General Phone	029 2090 3794
Opera Account	00000092
Email	Ross.Bowden@wales.nhs.uk
Order Number	726784476
Date Received	05/Aug/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38087	0111230	291148	Oxygen Analyser	Complete - Repaired Time :0.5 Hour(s)
Parts Replaced				
	Qty: 1	0121216		
	Qty: 0.5	0140004		

The AX300 Oxygen analyser has been repaired. The case and sensor input connector have been replaced.

Repair	Ref	S/N	Equipment Type	
SRN38088	0111230	322566	Oxygen Analyser	Report Only Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0180001		

The AX300 Oxygen analyser has been tested. The unit is working as expected.

Repair	Ref	S/N	Equipment Type	
SRN38089	0110017	571959	Oxygen Sensor	End Of Life Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0110017		

The R-17MED Oxygen sensor has been replaced with SN:267545.

Repair	Ref	S/N	Equipment Type	
SRN38090	0110017	953550	Oxygen Sensor	End Of Life Time :0 Hour(s)
Parts Replaced				
	Qty: 1	0110017		

The R-17MED Oxygen sensor has been replaced with SN:267546.

Service Repair Sheet 69200

Contact Name	Ross Bowden
Company/ Hospital Name	Cardiff and Vale UHB
Department	Clinical Engineering
Direct Phone	02921845678
General Phone	029 2090 3794
Opera Account	00000092
Email	Ross.Bowden@wales.nhs.uk
Order Number	726784476
Date Received	05/Aug/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38091	0131202	0014516	Misc. Cable	No Fault Found Time :0 Hour(s)

The Oxygen sensor cable has been tested. No fault was found.

Repair	Ref	S/N	Equipment Type	
SRN38092	0131202	0012289	Misc. Cable	No Fault Found Time :0 Hour(s)

The Oxygen sensor cable has been tested. No fault was found.
