

Service Repair Sheet SRS69200

Contact Name
Company/ Hospital Name
Department
Position
Direct Phone
General Phone
Opera Account
Email
Order Number
Date Received
Booked in By
Main Company
Type Return

Ross Bowden
Cardiff and Vale UHB
Clinical Engineering

02921845678
029 2090 3794
00000092
Ross.Bowden@wales.nhs.uk

05/Aug/2025
Robert Connor
Viamed
Quote

VIAMEDclean	
Goods In Only	
Decontamination certificate provided by customer	☒
Cleaned by Viamed, if no declaration certificate from customer	
Signed: _____	☒
Date: _____	
Goods Out Only	
Cleaned by Viamed before returning to customer	
Signed: _____	
Date: _____	

Notes 29/Jul/2025 Kate Griffiths

29/Jul/2025 Kate Griffiths

customer has 2 x AX-300i that no longer give readings. S/n: 291148 and 322566. They have tried replacing the cells/cables. Will ask for cert of decont. and no batteries

31/Jul/2025 Kate Griffiths

1Z43E45E6896981680 tracking number 31.7.25

05/Aug/2025 Robert Connor

Received 2 x AX300i s/n 291148, 322566, with 2 x base stand, 2 x coiled cable, 2 x flow diverter, 2 x R17MED s/n 953550, 571959, with 1 x blue tee.

Ready For quote

Repair Complete Signed

CGNEEN 18-11-8-25

CGNEEN 3-9-25

SRN	Equipment	Stock Ref	Serial Number	Warranty
SRN38087	Oxygen Analyser	0111230	291148	2
SRN38088	Oxygen Analyser	0111230	322566	2
SRN38089	Oxygen Sensor	0110017	571959	2
SRN38090	Oxygen Sensor	0110017	953550	2
SRN38091	Misc. Cable	0131202	0014516	2
SRN38092	Misc. Cable	0131202	0012289	2

01400004 x 0.5 @ £90 = £47.50
S/N, SRS, SRN

0121216 x 1 @ £46.20
SRS, SRN.

01800001 x 1 @ £50
S/N, SRS, SRN

01400012 x 2 FOC
S/N's, SRS, SRN's

0110017 x 2 @
S/N'S, SRS, SRN'S
£54.40 each

* 01400025 x 2
S/N's, SRS, SRN's
UPS x 1 @ £12.