

★ Ryan Swaine 9 Issues 1 **Unread** 2 ISO Tasks 20.80 °C

         

 

Contacts

**Kemi Olaofe**

CID34233 Opera CID34233 Type:Vandagraph Retail

Kemi Olaofe 75 Delamere Road, , Manchester, , M19 3NZ, United Kingdom

Tel 07402 450588 GBP Retail Price List Vandagraph (0010)

 Log Call Add Issue

Proforma Credit Limit 0.00GBP

 Account Home Main Details Account Memos Sales History Stock References Cust./Supp. Returns Service Visits Distributor Agreements Documents Files Linked Issues Regulatory Agreements

SRS69216

SRS Created : 18 Aug 2025

Created By Ryan Swaine

Add Watch

[Print Barcodes](#)[Print A4 Sheet](#)[Split Items into Different SRS Numbers](#)[Edit Details](#)

Upload Document to SRS

ADD DOCUMENT TO SRS : Document Description	Choose a file to upload: Choose file No file chosen
Next	

Handle with care

Add Items to Supplier Returns Box

- ☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs
- ☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Service Repair Sheet 69216

Company / Hospital	Kemi Olaofe
Contact Name	Kemi Olaofe
Department	
Position	
Company Phone	07402 450588
Direct Phone	07402 450588
Opera Account	CID34233
Email	divestuff@kemisola.me.uk
Order Number	
Viamed ORD Number	
Date Received Into building	20 Aug 2025
Type	Quote Before Repair Move to Repair
Issues?	

Notes

18/Aug/2025 Ryan Swaine

18/Aug/2025 Ryan Swaine

TEK-OX TX3275 will not turn on. Quote for repair

20/Aug/2025 Robert Connor

Received 1 x tek-ox s/n TX3275, with blue tee and hard yellow case.

22/Aug/2025 Catherine Spence

with engineer

Items for Repair

...

SRN	Equipment	Stock Reference	Barcode	Serialnumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN38134	Vandagraph Tek Ox	7910201 Requires Service Manual Linking in System	 1663151	TX3275	Oxygen Analyser Tek-Ox + Quick-Ox	Yes	No	Unfinished		00:00

Currently Viewing ITEM SRN38134 Vandagraph Tek Ox 7910201 TX3275 Oxygen Analyser Tek-Ox + Quick-Ox

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	Non added Yet	Non added Yet

-

ISO REVIEW

Please Select

Instructions