














John Orr

 CID20081 Opera CID20081 Type:Vandagraph Retail

John Orr 29 Levin Close, Hook, Haverford West, , SA62 4LF, UK

Tel 01437 899937 GBP Retail Price List Vandagraph (0010)

Proforma Credit Limit 0.00GBP



Add Issue

Account
Home

 Main Details

Account Memos

Sales
History

Stock References

[Cust./Supp. Returns](#)

Service Visits

Distributor Agreements

Documents
Files

 **Linked Issues**

Regulatory Agreements

SRS69219

SRS Created : 26 Aug 2025

Created By Ryan Swaine

Add Watch

[Print Barcodes](#)[Print A4 Sheet](#)

Split Items into Different SRS Numbers

[Edit Details](#)

Upload Document to SRS

Handle with care

Add Items to Supplier Returns Box

Add

ADD
DOCUMENT
TO SRS :
Document
Description

Choose a file to upload: No file chosen

☐ Return for Credit / Return to Stock
Unopened - will apply to all items on srs

☐ Clear From System - Force from System.
- will apply to all items on srs

Add notes to SRS

Add Notes

Linked to Order Reference 🔍 **158858**

Service Repair Sheet 69219		Notes
Company / Hospital	John Orr	26/Aug/2025 Ryan Swaine
Contact Name	John Orr	
Department		26/Aug/2025 Ryan Swaine
Position		VN202 mk.1 sn. 3529. Replace battery lead and sensor cable (connector is bent). Please pass to MG upon receipt
Company Phone		28/Aug/2025 Ryan Swaine
Direct Phone	07775433414	RS to add base plate screws for a TEK-OX upon return
Opera Account	CID20081	01/Sep/2025 Robert Connor
Email	johnorr18@hotmail.com	Received 1 x VN202 s/n VN3529, battery leads severed from unit.
Order Number		04/Sep/2025 Sophie Lines
Viamed ORD Number		John called for an update - Ryan to call him back once he has spoken to Michael. His home number is 01437 899937
Date Received Into building	01 Sep 2025	
Type	Repair Approved	

Issues?

Items for Repair										
...										
SRN	Equipment	Stock Reference	Barcode	SerialNumber	Description	Warranty New	Warranty Repair	Status	Repair Code	Time (H:M)
SRN38144	Oxygen Analyser VN202	7910100 Requires Service Manual Linking in System		VN3529	VN202 Mk 1	No	No	Unfinished		00:00

Currently Viewing ITEM **SRN38144 Oxygen Analyser VN202 7910100 VN3529 VN202 Mk 1**

[Create a Meeting Issue](#)

Items Requested for Repair	Item notes	Engineer Notes	Notes To Customer
	Non Supplied	Non added Yet	Non added Yet

ISO REVIEW

Instructions

Please Select