

# North Middlesex University Hospital **NHS**

NHS Trust

North Middlesex University Hospital

Clinical Engineering

Main Building Floor Level [-1]

Sterling Way, London N18 1QX

Email: kamal.pacitti@nhs.net

Tel: 020 88872582

Date of dispatch: 09/09/2025

Our WO#: 133151, 133152 & 133153

To: Viamed LTD,  
15 Station Road, Cross Hills,  
Keighley, BD20 7DT

Contact Name: Service Dept

E-mail: cathy.green@viamed.co.uk

Tel: 44 (0)1535 634 542

Dear..... Service Dept- SRS69238

Please find enclosed equipment X3 Blenders

Serial No's: B1307012, B1307009 & B1306996

Please quote us for the cost of the repair by e-mail, so that we can provide you with an order number.

Fault description: X3 Blenders for overhauling/service.

## DECONTAMINATION (Please tick one)

- A) This equipment is NOT as far as I am aware contaminated by any potentially infected material (eg. Blood/body fluids)
- B) The equipment may be contaminated by potentially infected material (eg. Blood/body fluids) and has been decontaminated externally, in accordance with the North Middlesex Hospital trust Policy.
- C) The equipment may be contaminated with potentially infected material (eg. Blood/body fluids) but could not be decontaminated.

Contaminated/potentially hazardous equipment must be despatched in a sealed container/bag

TRANSPORT/COURIERS NAME: TNT

PRINT: \_\_\_\_\_

SIGN: \_\_\_\_\_

DATE: \_\_\_\_\_