

Service Repair Sheet 69241

Contact Name	Rachel Rock
Company/ Hospital Name	Torbay and South Devon NHS
Department	Clinical Engineering Service, Contract Management Section
Position	Contracts Manager
Direct Phone	01803654107
General Phone	01803614567
Opera Account	00005130
Email	rachel.rock1@nhs.net
Order Number	01414
Date Received	17/Sep/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	
SRN38173	1410000	PR065A10	Foetal Simulator	Complete - Repaired Time :0 Hour(s)
Parts Replaced				
	Qty: 1	1480000		
	Qty: 1	1430309		

V1000 has had transducer interface cushion replaced and calibration has been checked.
