

Service Repair Sheet 69193

Contact Name	Manu Karumalil John
Company/ Hospital Name	Darcy Healthcare
Direct Phone	07404138177
General Phone	03308189300
Opera Account	CID33497
Email	manu.john@darcyhealthcare.com
Date Received	27/Aug/2025
Booked in By	Robert Connor

Repair	Ref	S/N	Equipment Type	Functional Check
SRN38138	0111263	GC48099014	Oxygen Monitor	Time :0 Hour(s)

Parts Replaced

Qty: 1 0180050

A functional check has been performed on the MAXO2 ME Oxygen monitor. The unit is working as expected.

Repair	Ref	S/N	Equipment Type	No Fault Found
SRN38139	0131700	Tracking5	Misc. Cable	Time :0 Hour(s)

The MAXO2 ME sensor cable has been tested. No fault was found.

Repair	Ref	S/N	Equipment Type	End Of Life
SRN38140	0110452	GC25399015	Oxygen Sensor	Time :0 Hour(s)

Parts Replaced

Qty: 1 0110452

The MAX-550E Oxygen sensor has been replaced with SN:LE55599144.
